



THE FOLLOWING IS A NON-COMPREHENSIVE LIST OF ITEMS SUGGESTED FOR INSTALLING THE SAM P. IT IS THE INSTALLER'S RESPONSIBILITY TO UNDERSTAND THE INSTALLATION PROCESS AND THE TOOLS REQUIRED PRIOR TO PERFORMING THE WORK.

SNAP RING PLIERS	MACHINIST LEVEL & BUBBLE LEVEL	CHALK TO MARK PEDESTAL LOCATION
1 1/16" HEX WRENCH	HAMMER DRILL	BANDING SHEAR FOR PALLET DISASSEMBLY
1 1/2" HEX WRENCH	1" CONCRETE BIT	FISH TAPE FOR ROUTING HOSES
2 1/4" HEX WRENCH	VACUUM TO CLEAR ANCHOR BOLT HOLES	EYE BOLTS FOR LIFTING PEDESTAL
3" HEX WRENCH	EXTENSION CORDS	SLINGS
3/8" ALLEN HEX	LADDERS	PERSONAL PROTECTIVE EQUIPMENT
5/8" ALLEN HEX	MAN LIFT	3/4-10 X 4 ALIGNMENT STUDS TO HELP ALIGN THE SAM ONTO THE PEDESTAL
TORQUE WRENCH	PLUMBING TOOLS	FORKLIFT OR CRANE TO LIFT THE SAM INTO POSITION
C-CLAMPS	ELECTRICAL TOOLS	
DRILL	LAYOUT PRINT & TAPE MEASURE	

ALL DESIGNS, SKETCHES AND DRAWINGS ARE THE PROPERTY OF POSITECH CORPORATION LETTING, OR ALLOWING TO BE LET, THE KNOWLEDGE FOR DESIGN AND/OR FABRICATION FROM SAID DESIGNS, SKETCHES OR DRAWINGS WITHOUT THE WRITTEN CONSENT OF POSITECH CORPORATION IS EXPRESSLY FORBIDDEN.



SAM K INSTALLATION INSTRUCTIONS			
SCALE: 1:24	DATE: 23-Apr-2014	DRAWN BY: WAK	
CLASS CODE: 725	DWG NO: SAM K INSTALL	SHT: 1 of 1	REV: